

24hrs ETA Update 6hrs  
ETD Update



FOR-12-109B VMI Rev 1

## Vessel Movement Information (VMI)

This document is required a minimum of 24hrs prior to ETA & a minimum of 6hrs prior to ETD

Ships PILOT CARD must be emailed with Arrival VMI

email to shipping@northport.co.nz

Vessel Name:	BERGE RISHIRI	IMO Number:	9713222
Masters Name:	LI ZHENGYANG	Ships Email:	master.rishiri@bergevessel.com

### Vessel Particulars

Hull Type:	Bulk	YES	Container		Tanker		Cruise		Other	
LOA:	179.97	LBP:	174	Beam:	30	Depth:	14.05			
Gross Tonnage:	21,530	Deadweight:	35172							
Bridge to Stern (m):	26.419	Lowest Freeboard:	4033 mm							
SWL Fwd Bitts:	52 T (center lead: 64 T)	SWL Aft Bitts:	52 T (center lead: 64 T)							
Thruster(s) Location:	NA	Thruster(s) Power:	NA							

### Current Conditions:

	ARRIVAL	DEPARTURE
Displacement:	39670	43760
Draft F (m):	8.57	9.63
Draft M (m):	9.21	10.04
Draft A (m):	9.78	10.42
KM (keel to Metacentre):	12.82	12.65
KGs:	9.78	10.73
Keel to C of G uncorrected for free surface allowance		
GMs:	3.04	1.91
Centre of Gravity to Metacentre (GMs=KM-KG)		
GMf:	2.44	1.61
C of G Metacentre corrected for free surface allowance		

### Navigation & Pilotage

Pilot ladder meets current IMO Res A.1045(27) & NZ Maritime Rule Part 53:	Yes
List any deficiencies or restrictions that could affect safe navigation:	Nil
Has the vessel been detained in the last 2 years, provide details:	Nil
Has the vessel had any main engine, generator or steering failures in the last 90 days, provide details:	No

Vessel is required to test all navigational, ships whistle, propulsion and steering equipment prior to Pilot boarding.

### Cargo Operations

Are there any significant risks, hazards or defects onboard that could affect the safety of cargo operations:	Nil
---------------------------------------------------------------------------------------------------------------	-----

Any other information:	
------------------------	--

By completing this form, the ship's Master confirms all data provided is true & correct at the time of issue. Failure to provide the correct information or if it is issued late, the pilotage could be delayed or cancelled, with all costs to the ship's account. The Master must inform Whangarei Harbour Radio immediately of any changes or updates to the ship's navigational status.

Document Completed By: MASTER ☒ Agent ☐ Date & Time: 05-Aug-2024 1500LT

