24hrs ETA Update 6hrs ETD Update

Vessel Movement Information (VMI)

Vessel Movement Information (VMI)

This document is required a minimum of 24hrs prior to ETA & a minimum of 6hrs prior to ETD

Ships PILUI	CARD	must be	ematted	WILL P	mvai	VIVII			email	to sni	pping	enompo		
Vessel Name:		RUBY		IMO Number:			9774032							
Masters Name:							erprise@fleetmail.inmarsat.com							
	D. II.		Canta		Ves	sel Particulars Tanker	_	r	C	uise	Т	Other	,	
Hull Type: LOA:	Bulk 176.8	2244	Conta	THE STATE OF THE	.50M	Beam:	3)	28.80M	S10		oth:		20M	
500000000000000000000000000000000000000	1750, 25522	SOM	0.7255		.50101		walo		24994		DIII.	14.	LOIN	
Gross Tonnage: 21162A Bridge to Stern (m): 24.51A							eadweight: est Freeboard:			6.0M				
Bridge to Stern (m): 24.51/ SWL Fwd Bitts: 510KN / 6					SWL Aft Bitts:			510KN / 628KN						
Thruster(s) Location: NIL				ZOKIN	Thruster(1000000						
inruster(s) Loc	allon.	MIL			Curre	ent Conditions		ower.	1					
						ARRIVAL					DEPA			
Displacement:					32277MT					41856MT				
Draft F (m):					7.90M					9.92M				
Draft M (m):					7.95M					10.08M				
Draft A (m):					8.20M					10.24M				
KM (keel to Metacentre):					12.61M					12.03M				
KGs: Keel to C of G uncorrected for free surface allowance					8.29M					10.63M				
GMs: Centre of Gravity to Metacentre (GMs=KM-KG)					4.32M					1.40M				
GMf: C of G Metacentre corrected for free surface					3.88M					1.03M				
Pilot ladder meet	ts current	IMO Re	s A.1045(2	27) & N		ritime Rule Po					Y	ES		
List any deficiencies or restrictions that could affect safe navigation:									NO					
Has the vessel been detained in the last 2 years, provide details:									NO					
Engine/Shaft I	Power Li	imiters	Can the	vesse	l attaiı	n posted eng	jine F	RPM for I	Pilotag	e:		YES		
				107					Vi elle		TO THE SAME			
Has the vessel ha	d any mo	ain engi	ne, gener	ator o	r steer	17 x 17 /willia la	the	last 90 c	lays, pr	ovide	details:			
						NO							1000-11	
Vessel is requ	ired to te	st all na	vigationo	II, ship:				d steerin	g equip	oment	prior to	Pilot boo	irding.	
Are there any sign	nificant ris	sks haze	ards or de	fects		go Operations		ect the s	afety a	f cara	o oper	ations:		
Are mere drift sign	illicarii il	iks, HGZC	J1 43 61 46	10015	511500	NO			5,5.1					
Any other infor	mation:													
By completing the the correct inform the master must	nation or it	f it is issue	ed late, th	e pilot	tage c	ould be delay	yed o	or cance	elled, wi	ith all c	osts to	the ship's	account.	
Document Co	omplete	d By:	MAS	TER	V	Agent		Dat	te & Ti	me:	2025	:04.10	10:00	

