

24hrs ETA Update 6hrs
ETD Update



FOR-12-109B VMI Rev 2

Northport

Vessel Movement Information (VMI)

This document is required a minimum of 24hrs prior to ETA & a minimum of 6hrs prior to ETD

Ships PILOT CARD must be emailed with Arrival VMI

email to shipping@northport.co.nz

Vessel Name:	KEN OLIVE	IMO Number:	1041984
Masters Name:	Capt. Emmanuel I. Andres	Ships Email:	ken-olive@super-hub.com

Vessel Particulars

Hull Type:	Bulk	x	Container		Tanker		Cruise		Other	
LOA:	179.98 m	LBP:	177.20m	Beam:	32.26m	Depth:	15.20m			
Gross Tonnage:	26014				Deadweight:		42774			
Bridge to Stern (m):	28.36m				Lowest Freeboard:		4.2			
SWL Fwd Bitts:	54 tons				SWL Aft Bitts:		54 tons			
Thruster(s) Location:	N/A				Thruster(s) Power:		N/A			

Current Conditions:

	ARRIVAL	DEPARTURE
Displacement:		51817
Draft F (m):		10.69
Draft M (m):		10.98
Draft A (m):		11.10
KM (keel to Metacentre):		13.9
KGs: <small>Keel to C of G uncorrected for free surface allowance</small>		12.1
GMs: <small>Centre of Gravity to Metacentre (GMs=KM-KG)</small>		1.80
GMf: <small>C of G Metacentre corrected for free surface allowance</small>		1.69

Navigation & Pilotage

Pilot ladder meets current IMO Res A.1045(27) & NZ Maritime Rule Part 53:	YES
List any deficiencies or restrictions that could affect safe navigation:	NIL
Has the vessel been detained in the last 2 years, provide details:	NIL

Engine/Shaft Power Limiters

Can the vessel attain posted engine RPM for Pilotage: YES

NO POWER LIMITER

Has the vessel had any main engine, generator or steering failures in the last 90 days, provide details:	NIL
Vessel is required to test all navigational, ships whistle, propulsion and steering equipment prior to Pilot boarding.	

Cargo Operations

Are there any significant risks, hazards or defects onboard that could affect the safety of cargo operations:	NIL
Any other information:	NIL

By completing this form, the ship's Master confirms all data provided is true & correct at the time of issue. Failure to provide the correct information or if it is issued late, the pilotage could be delayed or cancelled, with all costs to the ship's account. The Master must inform Whangarei Harbour Radio immediately of any changes or updates to the ship's navigational status.

Document Completed By: MASTER ☒ Agent ☐ Date & Time: 8/27/2025 10:00