

24hrs ETA Update
6hrs ETD Update



FOR-12-109B VMI Rev 1

Northport

Vessel Movement Information (VMI)

This document is required a minimum of 24hrs prior to ETA & a minimum of 6hrs prior to ETD

Ships PILOT CARD must be emailed with Arrival VMI

email to shipping@northport.co.nz

Vessel Name:	MV LIGNUM WEB	IMO Number:	9973054
Masters Name:	PAUL C. TOLEDO III	Ships Email:	master.lignumweb@fleetmail.inmarsat.com

Vessel Particulars

Hull Type:	Bulk	X	Container			Tanker			Cruise			Other	
LOA:	183.00 M		LBP:	180.00 M		Beam:	32.20 M		Depth:		15.40 M		
Gross Tonnage:		26,634 MT				Deadweight:		43,888.30 MT					
Bridge to Stern (m):		27.50 M				Lowest Freeboard:		4.75 M					
SWL Fwd Bitts:		765 KN / 76.58 T				SWL Aft Bitts:		765 KN / 76.58 T					
Thruster(s) Location:						Thruster(s) Power:							

Current Conditions:

	ARRIVAL	DEPARTURE
Displacement:		52,641 MT
Draft F (m):		10.51
Draft M (m):		10.63
Draft A (m):		10.69
KM (keel to Metacentre):		13.95
KGs:		11.43
<small>Keel to C of G uncorrected for free surface allowance</small>		
GMs:		2.52
<small>Centre of Gravity to Metacentre (GMs=KM-KG)</small>		
GMf:		2.45
<small>C of G Metacentre corrected for free surface allowance</small>		


Navigation & Pilotage

Pilot ladder meets current IMO Res A.1045(27) & NZ Maritime Rule Part 53:	YES
List any deficiencies or restrictions that could affect safe navigation:	NO
Has the vessel been detained in the last 2 years, provide details:	NO
Has the vessel had any main engine, generator or steering failures in the last 90 days, provide details:	NO

Vessel is required to test all navigational, ships whistle, propulsion and steering equipment prior to Pilot boarding.

Cargo Operations

Are there any significant risks, hazards or defects onboard that could affect the safety of cargo operations:	NO
Any other information:	



By completing this form, the ship's Master confirms all data provided is true & correct at the time of issue. Failure to provide the correct information or if it is issued late, the pilotage could be delayed or cancelled, with all costs to the ship's account. The Master must inform Whangarei Harbour Radio immediately of any changes or updates to the ship's navigational status.

Document Completed By: MASTER ☒ Agent ☐ Date & Time: DECEMBER 22, 2024 / 1910 LT