24hrs ETA Update 6hrs **ETD Update** 

## Northport Vessel Movement Information (VMI) This document is required a minimum of 24hrs prior to ETA & a minimum of 6hrs prior to ETD

Ships PILOT CARD must be emailed with Arrival VMI										email to shipping@northport.co.nz				
Vessel Name:	٨	AV CHA	MCHURI NA	AREE	REE IMO Num		nber:		929627					
Masters Name:		5	-				nurinaree@speedmailplus.com							
Vessel Particulars														
Hull Type:	Bulk	X	Contai	ner		Tanke	er		Cruis	se		Other		
LOA:	176.	.83	LBP:	169.5	В	eam:		28.8		Dep	oth:	14.2		
Gross Tonne	Deadweight:													
Bridge to Stern (m): 24.51							Freeb	oard:	3.92 m					
SWL Fwd Bollards: 64 T Thruster(s) Location: N/A				SWL Aff Bolle			ft Bollo	ards:			64	T		
Thruster(s) Loca	Thruster(s) Power: Current Conditions:				ower:	N/A								
						Conditions RRIVAI			1		DEDAD	TIIDE		
Displacement:				20288.56					DEPARTURE 42219,27					
Draft F (m):				6.76					9.86					
Di	7.88					10.07								
Di	8.99					10.28								
KM (kee	12.519					11.85								
KGs: Keel to C of G uncorrected for free surface allowance				8.47					10.848					
GMs: Centre of Gravity to Metacentre (GMs=KM-KG)				4.04					0.979					
Commo di Ciavily lo Mola														
C of G Metacentre correc	3.918					0.88								
Navigation & Pilotage Pilot ladder meets current IMO Res A.1045(27) & NZ Maritime Rule Part 53:											YE	<u> </u>		
i iloridadoi meets cuitem imo kes A.1045(21) & M. Maniline kule ran 33.														
List any deficiencies or restrictions that could affect safe navigation:									NO					
, , , , , , , , , , , , , , , , , , , ,														
Has the vessel been detained in the last 2 years, provide details:									NO					
, = === , =============================														
Has the vessel had any main engine, generator or steering failures in the last 90 days, provide details:														
NO														
Vessel is required to test all navigational, ships horn, propulsion and steering equipment prior to Pilot boarding.														
						perations								
Are there any significant risks, hazards or defects onboard that could affect the safety of cargo operations:														
NO														
Any other inform	nation:													
Pulconen	leting this fa	orm the al	nine Master	confirms all	datanra	widad is	truo º -	correct at t	he time of	iccus	Egiluro to	nrovido.		
By completing this form, the ships Master confirms all data provided is true & correct at the time of issue. Failure to provide the correct information or if it is issued late, the pilotage could be delayed or cancelled, with all costs to the ships account.  The Master must inform Whangarei Harbour Radio immediately of any changes or updates to the ship's navigational status.														
Document Co	mpleted I	Ву:	MAST	ER X	A	gent		Dat	e & Time	e:		17-03-24		



